

PHONE +852 2910 6174
FAX: +852 2910 1180
AFS address VHHHYOYX
E-mail aic@cad.gov.hk

HONG KONG SPECIAL ADMINISTRATIVE REGION

PEOPLE'S REPUBLIC OF CHINA

Aeronautical Information Service
Air Traffic Management Division
Civil Aviation Department
Hong Kong International Airport

AIP
SUPPLEMENT
A 21/07
22 November 2007

HONG KONG INTERNATIONAL AIRPORT
RUNWAY 07R/25L RESURFACING PROGRAMME
REVISED RUNWAY CLOSURE PERIODS
(Revisions are indicated in italics)

1. Introduction

- 1.1 Runway 07R/25L is closed for resurfacing during overnight periods from 1 September 2007 to 30 April 2008. *The runway closure periods are revised with effect from 29 November 2007.*

2. Runway Surface Condition

- 2.1 During RWY 07R/25L operational hours there will be no restrictions to available distances, and all runway lighting and visual markings will be maintained. Pilots should note that there will be periods when some resurfaced areas will not be grooved; therefore parts of the runway surface may be slippery when wet.

3. Runway Closure Programme

- 3.1 Throughout the resurfacing period, RWY 07R/25L will be closed for five nights a week for resurfacing work and RWY 07L/25R will be closed for two nights a week for regular maintenance work.
- 3.2 Full details of the runway closure programme are given below.

Runway	Closure Period	Nights of Closure
RWY 07R/25L (South Runway)	<i>1700-0030 (UTC)</i>	Every Monday/Tuesday, Tuesday/Wednesday, Thursday/Friday, Friday/Saturday, Saturday/Sunday
RWY 07L/25R (North Runway)	<i>1700-0030 (UTC)</i>	Every Sunday/Monday, Wednesday/Thursday

4. Runway Crossing for Taxiing Aircraft

- 4.1 When RWY 07R/25L is closed, taxiing aircraft will be able to cross the runway at one or more of the following points:
- a) RWY 07R threshold via TWY H1 and TWY K1;
 - b) Runway mid-point via TWY J5 and TWY K3;
 - c) RWY 25L threshold via TWY J10 and K5.
- 4.2 The contractor has been instructed that vehicles must give way to aircraft at all times and there should be no foreign object on any taxi route. However, pilots should remain vigilant and keep a good look-out when crossing the runway.

5. Airport Availability during Runway Closure Periods

- 5.1 When RWY 07R/25L is closed and resurfacing work has commenced, the runway will **not** be available for return to service until the scheduled time. In the event that the operational runway (RWY 07L/25R) becomes unavailable due to unforeseen circumstances, the airport will be closed for all fixed wing operations.

6. Revisions to Resurfacing Programme

- 6.1 The resurfacing programme will be suitably revised during holiday periods, e.g. Christmas and New Year. The resurfacing programme may also be subject to revisions at short notice in the event of forecast or actual adverse weather conditions, or other extenuating circumstances.
- 6.2 Any changes to the resurfacing programme will be promulgated by NOTAM.

7. *This supersedes AIP Supplement A17/07 at 0711291600 UTC.*