
HONG KONG SPECIAL ADMINISTRATIVE REGION
PEOPLE'S REPUBLIC OF CHINA
AERONAUTICAL INFORMATION SERVICE
(ISO 9001 CERTIFIED)

PHONE +852 2910 6174
FAX +852 2910 1180
AFS VHHHYOYX
EMAIL aic@cad.gov.hk

AIR TRAFFIC MANAGEMENT DIVISION
CIVIL AVIATION DEPARTMENT
HONG KONG INTERNATIONAL AIRPORT


AIP Supplement
A 08/10
30 July 2010

HONG KONG INTERNATIONAL AIRPORT
HANDLING OF CODE F AIRCRAFT

- 1 Hong Kong International Airport is classified as a Code F airport in accordance with the requirements of ICAO Annex 14. Notwithstanding this, there are some taxiways that only comply with Code E requirements due to the width of the taxiway shoulders.
2. The following operating procedures apply to Code F aircraft (Airbus A380 and Boeing 747-8) at Hong Kong International Airport.
 - 2.1 AIRBUS A380
Both runways and the Code F taxiways, apron taxilanes and parking stands as shown in the attached Aerodrome Chart are available for use by A380 aircraft.
 - 2.2. BOEING 747-8
Both runways and Code E taxiways and apron taxilanes (i.e. ALL taxiways and taxilanes) may be used by Boeing 747-8 aircraft. However only Code F parking stands as shown on the attached Aerodrome Chart are available for use by Boeing 747-8 aircraft.
3. **This supersedes AIP Supplement A01/10**

HONG KONG INTERNATIONAL AIRPORT

AERODROME CHART



- Code F Runway, Taxiway/Taxilane
- Code F Parking Stand (E15, N60, N62, C9, C10, C33, C34)

19 July 2010